

2017 Ford Mustang V8-5.0L

Vehicle > Technical Service Bulletins

ALUMINUM PANEL CORROSION

TSB 17-0062	ALUMINUM PANEL CORROSION
Publication Date: August 23, 2017	

2000-2003 Ranger

2005-2006 Ford GT

2000-2007 Crown Victoria, Taurus

2007-2010 Explorer Sport Trac

2000-2017 Expedition

FORD: 2002-2017 Explorer

2004-2017 F-150

2005-2017 Mustang

2013-2017 Fusion

2015-2017 Edge

2017 F-Super Duty

2000-2006 Lincoln LS

2000-2007 Town Car

LINCOLN: 2010-2016 MKT

2000-2017 Navigator

2013-2017 MKZ

2016-2017 MKX

2003-2004 Marauder

MERCURY: 2000-2007 Grand Marquis

2002-2007 Sable

2002-2010 Mountaineer

This article supersedes TSB **16-0028** to update the update the model years, Issue Statement and Service Procedure

ISSUE:

Some 2000 and newer Ford, Lincoln and Mercury vehicles equipped with aluminum body panels may exhibit corrosion concerns appearing as bubbled and/or peeling paint with or without accompanying white dust. Panel replacement is recommended.

ACTION:

Follow the Service Procedure steps to correct the condition.

SERVICE PROCEDURE

1. Remove the affected panel. Refer to the appropriate Workshop Manual (WSM), Section as required.
2. Remove the new panel from the packaging and clean thoroughly using products recommended in your Ford approved paint system technical manual.
3. Apply Lord Fusor® 123EZ, 3M™ 08329 or equivalent sealer. Allow it to flash per the sealer technical data sheet (TDS) information.

4. Scuff sand the entire panel, then clean and apply the primer or sealer as recommended by your paint system.
5. Mix and apply the base coat and clearcoat following your Ford approved paint system technical information.
6. Install the new panel. Refer to the appropriate WSM section as required.

Obtain Locally	
Part Number	Part Description
123EZ	Lord Fusor® Non-Sag Seam Sealer (Medium)
08329	3M™ Control-Flow Seam Sealer

WARRANTY STATUS

Information Only

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford or Lincoln dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supercede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.

Copyright © 2017 Ford Motor Company