

2017 Ford Mustang V8-5.0L

Vehicle > Technical Service Bulletins

CONVERTIBLE - ROOF SAGGING AT THE REAR GLASS

TECHNICAL SERVICE BULLETIN CONVERTIBLE - ROOF SAGGING AT THE REAR GLASS

18-2036
06 February 2018

This bulletin supersedes 16-0104. Reason for update: Concern Carryover to New Model

Model:

Ford
2015-2018 Mustang

Summary

This article supersedes TSB 16-0104 to update the model years.

Issue: Some 2015-2018 Mustang vehicles with a convertible top may exhibit a condition where the top sags on one or both sides near the rear glass due to broken tension rod clips.

Action: Follow the Service Procedure steps to correct the condition.

Parts

Part Number	Description	Quantity
FR3Z-76422B34-A	Clip	2
FR3Z-7640380-A	Foam Block	1

Warranty Status: Eligible Under Provisions Of New Vehicle Limited Warranty Coverage Warranty/ESP coverage limits/policies/prior approvals are not altered by a TSB. Warranty/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

Labor Times

Description	Operation No.	Time
2015-2018 Mustang: Install Rear Glass Tension Rod Clips And Foam Block Following The Service Procedure (Do Not Use With Any Other Labor Operations)	182036A	0.9

Repair/Claim Coding

Causal Part:	76422B34
Condition Code:	01

SERVICE PROCEDURE

1. Remove the rear seat backrest. Refer to Workshop Manual (WSM), Section 501-10.
2. Remove the rear quarter trim panels. Refer to WSM, Section 501-05.

3. Disconnect the convertible top tension belt from the rear bow. (Figure 1)

Figure 1

**4. Lift the headliner over the rear glass tension rods. (Figure 2)**

Figure 2


**5. Using a small flat blade screwdriver, pry the rear glass tension rod clips open and remove the clips. (Figure 3)**

Figure 3

**6. Install new clips onto the rear glass tension rod ends. Note the alignment rib and make sure the clips are oriented for proper installation into the rear glass frame. (Figure 4)**

Figure 4



7. Open the roof slightly to relieve tension and ease alignment between the rear glass tension rod and the rear glass frame.


8. Insert the rear glass tension rods into the rear glass frame. Verify the clip is installed securely into the frame and the locking tab is visible as shown. Use of a mirror may be necessary. Pull on the clip slightly to verify the clip is fully locked. (Figure 5)

Figure 5



9. Slightly press on the convertible top as shown to verify the rear glass tension rod is connected to the rear glass frame. (Figure 6)

Figure 6



10. Remove the plastic child seat tether covers. (Figure 7, A)

Figure 7



11. Position the parcel shelf up. Refer to WSM, Section 501-05

(1). It is not necessary to disconnect the convertible top tension belt adjuster bracket.

12. Install the foam block as shown. (Figure 7, B)

13. Position the parcel shelf down and install. Refer to WSM, Section 501-05.

14. Connect the convertible top tension belt. (Figure 1)

15. Cycle the convertible top twice from fully closed to fully open to make sure the rear glass tension rods remain properly attached to the rear glass frame.

16. Install the plastic child seat tether covers. (Figure 7, A)

17. Install the rear quarter trim panels. Refer to WSM, Section 501-05.

18. Install the rear seat backrest. Refer to WSM, Section 501-10B.

© 2018 Ford Motor Company

All rights reserved.

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford or Lincoln dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.