

1999 Ford Mustang GT V8-4.6L SOHC VIN X

Vehicle > Technical Service Bulletins

## CUP HOLDER - NOT DEEP ENOUGH TO HOLD LARGE CUPS

Article No.

99-15-3

INTERIOR-CUP HOLDER NOT DEEP ENOUGH TO

HOLD LARGE CUPS-VEHICLES BUILT THROUGH

51311999

FORD:1999 MUSTANG

### ISSUE

Some customers may have concerns that beverages will spill when put into the cup holder. This may be caused by the cup holder not being deep enough to fit large cups.

### ACTION

Replace the cup holder with a revised cup holder. The revised cup holder has increased depth to reduce the possibility of beverages spilling. Refer to the following Service Procedure for details.

### SERVICE PROCEDURE

1. Grasp center divider of cup holder (by hand) and pull straight up to remove the holder.
2. Make sure all spring clips were removed with old cup holder.
3. Install new Cup Holder (XR3Z-6313562-AAA) with new clips by aligning the rear alignment tab on holder with slot in center and press holder down firmly until all spring clips are seated.

F~j;;~NUMBER I      PARTNAME

XR3Z-6313562-AAA      cup Holder

OTHER APPLICABLE ARTICLES: NONE WARRANTY STATUS: Eligible Under The

Provisions Of Bumper To

Bumper Warranty Coverage

OPERATION	DESCRIPTION	TIME
991503A	Replace Cup Holder	0.2 Hr.

DEALER CODING

CONDITION

BASIC PART NO.	CODE
6313562	16

OASIS CODES: 107000