

SSM # 21-0616-AA

2020-2021 Roush RS3 Front Fender Canard Rubbing

Applicable Model(s)/VINs:

2020-2021 Roush RS3 Equipped with Magneride Suspension

Issue Description:

Some customers may experience rubbing of the front tires on the inside of the canard. This happens during aggressive maneuvering or harsh roads which may cause the tire to hit slighly on the front wheel canards.

Repair Action:

1. Remove front canard from vehicle by removing the three (3) bolts. No vehicle lift is necessary and it helps to turn the wheel to gain wheel clearance.



2. Measure on the TOP of the canard as shown, and make a cut line.





Repair Action Cont:

3. Trim using a cutoff wheel or suitable plastic trim tool and deburr as shown.



- 4. Reinstall canard on vehicle by reversing step 1
- 5. Repeat process for other side.

Limit of Liability Statement

The information contained in this publication was accurate and in effect at the time the publication was approved for printing and is subject to change without notice or liability. Roush Performance Products (RPP) reserves the right to revise the information presented herein or to discontinue the production of parts described at any time.