

**AUDIO CONTROL MODULE (ACM) DISPLAYS
SATELLITE FAULT WITH DIAGNOSTIC TROUBLE
CODE (DTC) B1342 IN SATELLITE DIGITAL AUDIO
RECEIVER SYSTEM (SDARS) MODULE**

TSB 11-3-3

FORD:

2008-2009 Fusion, Mustang, Taurus, Escape
2008-2010 Edge, Explorer Sport Trac,
Explorer, F-250, F-350, F-450, F-550
2008-2011 Expedition, Ranger
2010-2011 E-150, E-250, E-350, E-450

2008-2010 MKX
2008-2011 Navigator

MERCURY:

2008-2009 Milan, Sable, Mariner
2008-2010 Mountaineer

LINCOLN:

2008-2009 MKZ

ISSUE

Some 2008-2011 Expedition, Navigator, Ranger,
2010-2011 E-Series Econoline, 2008-2010 MKX,
Edge, Explorer, Explorer Sport Trac, Mountaineer,
F-Super Duty, 2008-2009 Fusion, Milan, MKZ,
Taurus, Escape, Mariner and Mustang vehicles
(without navigation) may exhibit no satellite
reception with SAT FAULT displayed in the ACM,
and a DTC B1342 set in the SDARS module.

OPERATION	DESCRIPTION	TIME
110303A	Reprogram The SDARS Module (Do Not Use With Any Other Labor Operations)	0.3 Hr.
DEALER CODING		CONDITION CODE
BASIC PART NO.		
18C963		04

ACTION

Reprogram the SDARS module to the latest calibration using IDS release 71.04 and higher. This new calibration is not included in the VCM 2011.1 DVD. Calibration files may also be obtained at www.motorcraft.com.

WARRANTY STATUS: Eligible Under Provisions Of New Vehicle Limited Warranty Coverage
IMPORTANT: Warranty coverage limits/policies are not altered by a TSB. Warranty coverage limits are determined by the identified causal part.

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford or Lincoln dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supercede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.