

2004 Ford Mustang V8-4.6L SOHC VIN X

Vehicle > Technical Service Bulletins

M/T - MERCON(R) V ATF USAGE INFORMATION

TSB 06-26-1

01/08/07

MERCON ATF IS BEING REPLACED BY MERCON V
AS A SERVICE FLUID FOR SOME MANUAL
TRANSMISSIONS

FORD:

1981-2003 Escort

1984-1995 Thunderbird

1985-2007 Mustang

1985-1996 Bronco

1985-2007 Ranger

1986-1997 Aerostar

1991-2004 Explorer

1995-2007 F-150

1996-2007 F-Super Duty

2001-2003 Explorer Sport Trac, Explorer Sport

LINCOLN:

2001-2002 Lincoln LS

MERCURY:

1984-1995 Cougar

1987-1999 Tracer

ISSUE

MERCON(R) Automatic Transmission Fluid is being replaced by MERCON(R) V as the service fluid for manual transmissions originally requiring MERCON(R).

ACTION

Beginning immediately all manual transmission applications requiring MERCON(R) can now be serviced using MERCON(R) V or MERCON(R) Automatic Transmission Fluid or dual usage fluids labeled MERCON(R) / MERCON(R) V. After July 1, 2007, MERCON(R) Automatic Transmission Fluid will no longer be manufactured, therefore, availability of this fluid will continue until remaining inventory has been depleted.

SERVICE PROCEDURE




Figure 1

Service manual transmissions requiring MERCON(R) with MERCON(R) V or MERCON(R) Automatic Transmission Fluid or dual usage fluids labeled MERCON/MERCON(R) V. For proper fluid application on current and past model manual transmissions refer to the fluid usage chart. (Figure 1)

WARNING

FULL SYNTHETIC MANUAL TRANSMISSION FLUID (XT-M5-QS), SAE 75W-90 API GL-4 GEAR OIL (XY-75W90-QGL) AND SAE 75W-90 PREMIUM SYNTHETIC TRANSAXLE LUBRICANT (XT-75W90-QGT) ARE UNIQUE FLUIDS AND MUST BE USED IN APPLICATIONS RECOMMENDING THAT PARTICULAR FLUID.

USE OF ANY OTHER FLUID MAY CAUSE REDUCED FUNCTIONALITY OR DAMAGE.

PART NUMBER	PART NAME
XT-2-QDX	MERCON® (Quart)
XT-5-QM	MERCON® V (Quart)
XT-2-DDX	MERCON® (55 Gallon Drum)
XT-5-DM	MERCON® V (55 Gallon Drum)

Parts Block

WARRANTY STATUS: Information Only

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the Bulletin applies to your vehicle.

Disclaimer