



540008

Installation of the Ford Speed Sensor Plug



1. Remove the retaining clip from the speed sensor which holds the speedometer cable in place. Pull out the speedometer cable and make sure the stock O-ring remains in place. NOTE: without the O-ring the sensor will leak.



2. Insert the sensor plug in place of the speedometer cable and re-insert the retaining clip to keep it in place.



3. Refer to the main manual for wiring instructions to complete the VHX installation.

⚠WARNING: This product can expose you to chemicals including lead, which is known to the State of California to cause cancer and birth defects or other reproductive harm. For more information go to www.P65Warnings.ca.gov



4510 W. 61st St. North
Sioux Falls, SD 57107
www.dakotadigital.com

dakotasupport@dakotadigital.com Copyright 2011 - Dakota Digital, Inc.

Phone (605) 332-6513
Fax (605) 339-4106