

1999 Ford Mustang GT V8-4.6L SOHC VIN X

Vehicle > Technical Service Bulletins

## ELECTRICAL - NEW TERMINAL GREASE RELEASED FOR SERVICE

Article No.

98-24-6

12/07/98

ELECTRICAL - NEW TERMINAL GREASE RELEASED  
FOR SERVICE

FORD:

1981-99 ESCORT

1983-99 CROWN VICTORIA

1984-88 EXP

1984-94 TEMPO

1985-99 TAURUS

1986-97 PROBE

1988-91 FESTIVA

1993-99 MUSTANG

1994-97 ASPIRE

1995-99 CONTOUR

1996-97 THUNDERBIRD

LINCOLN-MERCURY:

1983-99 CONTINENTAL, GRAND MARQUIS

1984-86 CAPRI

1984-87 LN7

1984-94 TOPAZ

1985-99 SABLE

1988-92 MARK VII

1991-94 CAPRI

1993-98 MARK VIII

1993-99 TRACER

1995-99 MYSTIQUE

1996-97 COUGAR, TOWN CAR

1999 COUGAR

MERKUR:

1985-88 XR4TI

1988 SCORPIO

LIGHT TRUCK:

1981-96 BRONCO

1981-97 F SUPER DUTY, F-250 HD, F-350

1981-99 ECONOLINE, F-150, F-250 LD

1983-99 RANGER  
1984-90 BRONCO II  
1984-97 AEROSTAR  
1991-99 EXPLORER  
1993-99 VILLAGER  
1995-99 WINDSTAR  
1997-99 EXPEDITION, MOUNTAINEER  
1998-99 NAVIGATOR  
1999 SUPER DUTY F SERIES

**MEDIUM/HEAVY TRUCK:**

1984-99 F & B SERIES  
1988-97 CARGO SERIES  
1996-98 AEROMAX, LOUISVILLE

**ISSUE**

Ford Motor Company has released a new Electrical Grease (F8AZ-19G208-AA) to reduce the possibility of moisture corrosion at the terminals.

**ACTION**

Add the new grease during electrical connection repair.

**CAUTION**

ELECTRICAL CONNECTOR GREASE SHOULD NOT BE USED IN HIGH VOLTAGE CONNECTIONS FOR SPARK PLUG AND COIL WIRE APPLICATIONS.

**PROPER USES OF THE NEW ELECTRICAL GREASE INCLUDE:**

^ Electrical Connectors

^ Battery Connections

^ Light Sockets

^ Starter Terminals

**DO NOT USE ON:**

^ Spark Plug Wires

^ Coil Wires

^ Spark Plug-to-Coil Connections

^ Low Current Flow Switches (12V Systems less than 0.1 amp)

**OTHER APPLICABLE ARTICLES: NONE**

**WARRANTY STATUS: INFORMATION ONLY**

**OASIS CODES: 201000, 201100, 201200, 202000, 203000, 203200, 204000, 205000, 601300**