

2000 Ford Mustang V6-3.8L VIN 4

Vehicle > Technical Service Bulletins

RECALL - SAFETY BELT RETRACTOR INSPECTION/REPLACEMENT

Related Links

Dealer Letter

Attachment I - Administrative Information

Attachment II - Labor and Parts Information

Attachment III - Technical Information

Attachment IV - Lincoln Commitment Announcement Letter

Owner Letter

SAFETY BELT RETRACTOR INSPECTION

AFFECTED VEHICLES:

CERTAIN 1999 MODEL YEAR TAURUS AND SABLE, 1999-2000 MODEL YEAR MUSTANG AND 2000 MODEL YEAR CONTINENTAL

OVERVIEW

Not all safety belt retractors require inspection. The safety belt retractors that will require inspection vary depending on the vehicle model. Refer to the "Safety Belt Inspection Chart" to determine which safety belt retractors are affected for the vehicle you are servicing.

NOTE:

Each safety belt within any one vehicle may have a different date code. Be sure to inspect each affected retractor.