2004 Ford Mustang V8-4.6L SOHC VIN X Vehicle > Technical Service Bulletins

A/T - TRANSMISSION COOLER FLUSH INFORMATION

General Service Bulletin (GSB): Transmission Cooler Flush

General Service Bulletin (GSB):	Transmission Cooler Flush									
GSB Overview:	This bulletin provides the process for using the transmission flush machine and provides an application reference chart.									
NOTE: This information is not intended to replace or supersede any warranty, parts and service policy, Work Shop Man- ual (WSM) procedures or technical training or wiring diagram information.										

Equipment Requirements —————	pg. 2
Unacceptable Flush Methods —————	pg. 3
Service Procedure	pg. 4-5
Front Wheel Drive Cooler Flush Chart ————	pg. 6-7
Rear Wheel Drive Cooler Flush Chart ————	pg. 8-9

Cooler Flush GSB

Version 2.0

December 2014

Page 1

Why flush transmission coolers?

The number one cause for repeat transmission repairs is contamination trapped in the transmission cooling system. After a repair is made, or a new transmission is installed, clean transmission fluid will break this contamination loose and deposit it into the transmission. For this reason it is important to always flush the transmission cooler and cooler lines using the **Rotunda Heated Transmission Cooler Line Flusher (Rotunda Tool number 222-00007) or equivalent**. This tool uses heated transmission fluid, as well as a pulsating action to break contaminants free and remove them from the system.

EQUIPMENT REQUIREMENTS

The transmission cooling system (cooler <u>and</u> lines) MUST be flushed every time the transmission is overhauled or replaced in order to minimize the likelihood of repeat repairs. It is mandatory that proper equipment and procedures (Workshop Manual section 307-01) be followed when flushing coolers and lines.

The flushing equipment used MUST:

- Maintain fluid at 140° F (60° C)
- Pulsate during cleaning.
- Have a GPM flow meter.
- Have twin magnetic filters.
- · Have air purge capability before and after flushing.
- Rotunda tool 222-00007 is recommended for this procedure.

Note - If the Transmission Heated Cooler Line Flusher or equivalent is not available, install a new transmission fluid cooler and/or auxiliary fluid cooler.

Cooler Flush GSB December 2014

Version 2.0 Page 2

Unacceptable Flush Methods

NEVER USE:

- Equipment not meeting the requirements specified in this bulletin.
- · Equipment that uses solvents to clean coolers.
- Equipment that is not heated to clean coolers.
- · Aerosol Solvents to clean coolers.
- Shop Air as a stand alone flush method to clean coolers.

Previous equipment to clean & flush coolers, lines and torque-converters used solvents to remove contamination.

There are two issues with this method:

- Residual solvent contamination can cause damage to friction bonding materials within the transmission (Clutches, Bands and Torque Converter Clutch).
- Lack of fluid heating and agitation prevents this method from completely removing contamination from lines, in-radiator coolers and auxiliary coolers (OTA).

Aerosol Solvents should never be used for several reasons.

- They do not provide the volume necessary to remove heavy contaminants.
- They evaporate quickly and essentially leave contaminants behind.

NOTE: Failure to use proper equipment or follow proper flush procedures may result in dealer charge back of repairs.

Cooler Flush GSB

Version 2.0

Page 3

Service Procedure

Notice - Before beginning this procedure, please determine if the cooler in the vehicle being serviced can be flushed. Refer to the charts on page 6 - 9 of this bulletin for information.

Preparation -

- The in-line transmission thermal by-pass valve (if equipped) must be removed for flushing.
- If an in-line filter has been installed on the vehicle, it will need to be removed before performing the flush procedure.
- Some 2003-2007 vehicles equipped with a 5R110 Torqshift transmission may have a remote filter (aluminum housing) that can be disassembled and cleaned. The cooler lines must be disconnected prior to flushing. Once flushing is complete, install a new filter element.
- Some 2008 vehicles with a 5R110 Torqshift transmission have a black can filter mounted in the bellhousing. The cooler lines must be disconnected at the filter housing prior to beginning the flush procedure. The filter must be replaced after completing the flush.
- 1. Begin by identifying the cooler return line. Refer to the charts below.

Rear Wheel Drive	Return Line Location
4R100	Rear case fitting
4R75E/4R70W/AODE	Top case fitting
Torqshift (5R110)	Rear case fitting
6R60/6R75/6R80	Top case fitting
6HP26	Top case fitting
Torqshift 6 (6R140)	Top case fitting
E4OD	Rear case fitting
4R44/55E	Top case fitting
5R55S/E/N/W	Top case fitting

Front Wheel Drive	Return Line Location
6F35	Lower case fitting
6F50/55	Rear case fitting
CD4E	Rear (Pump) end case fitting
4F27E	Rear (Cover) end case fitting
FNR5	Rear (Cover) end case fitting
Aisin AW21	Top case fitting
AXOD/AXODE	Bottom case fitting
AX4S/AX4N/4F50N	Bottom case fitting

Note: Follow equipment instructions, air purge cooler lines and cooler prior to starting flushing procedure. Use the Air purge valve and fluid purge valve with clear hose located on the flush equipment.

Cooler Flush GSB

Version 2.0

Page 4

Service Procedure (cont.)

- 2. Check and top off fluid level of the Transmission Heated Cooler Line Flusher tank with new, clean transmission fluid.
- 3. Allow the fluid in the flusher 15-30 minutes to heat up to 60° C (140° F) before using.
- 4. Install line adapter fittings to the transmission cooler lines.
- 5. Attach the flusher's blue line to the transmission return cooler line adapter fitting.
- 6. Attach the flusher's red line to the transmission outlet cooler line adapter fitting.
- 7. Located on the Flusher Machine is the fluid purge valve and hose. Purge the cooler and the cooler lines of contaminated fluid before starting the back flush procedure.
- 8. Allow the cooling system to back-flush for 15 minutes, and then flush the cooler in a forward/normal flow direction for an additional 10-15 minutes.

Note - The machine flow rate must be equal to or greater than the published cooler flow rates (View the flow meter located on the Transmission Heated Cooler Line Flusher). Refer to flushing instructions in the Workshop Manual.

For Transmission Heated Cooler Line Flusher (222-00007) ordering information, contact Rotunda at 800-ROTUNDA (800-768-8632) or https://rotunda.service-solutions.com

Cooler Flush GSB

Version 2.0 Page 5

December 2014

						FWD	Transa	xles									
				C	ooler F	lush o	Replac	emen	t Guid	e							
			Model Year														
Transmission	Vehicle	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014	2015
	Focus	F	F	F	F	F	F	F	F	F	F	F	F				
4F27E	Transit Connect											F	F	F	F		
	Freestar					F	F	F	F	F							
	Sable	F	F	F	F	F	F										
4F50N (AX4N)	Taurus	F	F	F	F	F	F	F	F								
	Windstar		F	F	F												
	Edge/MKX													F	F	F	F
	Escape										F	F	F	F	F	F	F
	Explorer													F	F	F	F
	Fusion/MKZ											F	F	F	F	F	F
	Mariner										F	F	F				
	Milan											F	F				
6F35	MKT														F	F	F
0133	Interceptor Sedan														F	F	F
	Interceptor Utility														F	F	F
	Taurus														F	F	F
	Transit Connect															F	F
	Edge/MKX								F	F	F	F	F	F	F	F	F
	Explorer												F	F	F	F	F
[Flex										F	F	F	F	F	F	F
[MKS										F	F	F	F	F	F	F
[MKT											F	F	F	F	F	F
6F50/55	Interceptor Sedan														F	F	F
	Interceptor- Utility														F	F	F
	Sable									F	F						
	Taurus									F	F	F	F	F	F	F	F
	Taurus X									F	F						

Legend:	
F	Flush cooler during transmission overhaul or replacement
R	Replace cooler during transmission overhaul or replacement
R (OTA)	Replace OTA cooler (If equipped) during transmission overhaul or replacement

Cooler Flush GSB

Version 2.0

December 2014

Page 6

							VD Tra										
	ı				Cool	er Flus	h or Re	placen									
							1		Mode	l Year							-
Transmission	Vehicle	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014	2015
AX4S	Sable/ Taurus	F	F	F	F												
V1000000000000000000000000000000000000	Windstar	F															
	Cougar	F	F	F	F												
CD4E	Escape		F	F	F	F	F	F	F	F							
	Mariner						F	F	F	F							
CVT	Five Hundred/ Freestyle/ Montego						R	R	R								
	Five Hundred/ Freestyle/ Montego						R	R	R								
AW21	Fusion							F	F	F	F	F	F	F			
	Milan							F	F	F	F	F	F				
AW21	MKZ								F	F	F	F	F	F			
	Sable																
	Fusion							F	F	F	F						
ENID5	Milan							F	F	F	F						
1141.5	MKZ							F	F	F	F						
	Zephyr							F									
	Hybrid/														F	F	F
HF35															F	F	F
	MKZ														F	F	F

<u>Legend:</u>	
F	Flush cooler during transmission overhaul or replacement
R	Replace cooler during transmission overhaul or replacement
R (OTA)	Replace OTA cooler (If equipped) during transmission overhaul or replacement
Note:	CVT remanufactured transmissions include the cooler specific to the vehicle application in the packaging.

Cooler Flush GSB	December 2014
Version 2.0	Page 7

					R	WD Tra	ansmis	sions									
				Cod	oler Flu	ush or	Replac	emen	t Guid	e							
									Mod	el Yea							
Transmission	Vehicle	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014	2015
	Blackwood			R (OTA)	R (OTA)												
	E-150	F	F	F	F	F											
	E250/350/450	F	F	F	F	F											
4R100	Excursion	R (OTA)	R (OTA)	R (OTA)	R (OTA)	R (OTA)	R (OTA)										
	Expedition/ Navigator	F	F	F	F	F											
	F-150	F	F	F	F	F											
	F250/350/450	R (OTA)	R (OTA)	R (OTA)	R (OTA)	R (OTA)											
	Explorer/ Mountaineer	R	R	R	R	R	R	R	F	F	F	F					
4R44/ 5R44/	Explorer Sport		R	R	R												
4R100	Explorer Sport- Trac		R	R	R	R	R										
	Ranger	R	R	R	R	R	R	R	F	F	F	F	F				
	Crown Victoria/ Grand Marquis	R	R	R	R	R	R	R	R	R	R	R	R				
	E-150	F	F	F	F	F	F	F	F	F	F	F	F	F	F	F	
	E250/350/450	F	F	F	F	F	F	F	F	F	F	F	F	F	F	F	
	Expedition	F	F	F	F	F	F	F									
4R70/75	Explorer/ Mountaineer	F	F														
	F-150	F	F	F	F	F	F	F	F	F							
	Marauder				R	R											
	Mustang	F	F	F	F	F											
	Navigator	F	F	F	F	F	F	F									
	Town Car	R	R	R	R	R	R	R	R	R	R	R	R				

Legend:	
F	Flush cooler during transmission overhaul or replacement
R	Replace cooler during transmission overhaul or replacement
R (OTA)	Replace OTA cooler (If equipped) during transmission overhaul or replacement


Cooler Flush GSB

Version 2.0

December 2014

Page 8

							nsmiss										
		_		Coo	ler Flus	h or R	eplace	ment (
		<u> </u>		_					Mode	l Year		_	_	_	_	_	_
Transmission	Vehicle	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014	201
	E-150					555	333	222	544	333.	***	***	333	533	***	16.6	
	E-250/350/450					223	222	222	222	222		***	222	222	222		22
	Excursion					222	222										
5R110	F-Series					***	***	***	•••	•••		***	***	***	•••		**
	Super Duty				***	***	XXX	777	533	733		***	***	ZZZ	***	***	22
	Low							:::	:::	::::							
	Cab Forward							-			***						-
	Aviator				R	R	R										
5R55N/W/S	Explorer/ Mountaineer			R	R	R	R	R	R	R	R	F					
	Explorer Sport-								-	-	-	-					
	Trac								F	F	1	F					
	Mustang						R	R	R	R	R	F					
	Lincoln LS	F	F	F	R	R	R	R									
	Thunderbird			F	R	R	R										
6HP26	Expedition/						P	R	R	D.							
0111 20							IX	IX	IX	- 11							
													F	F	F	F	F
6R140																	
5R55N/W/S Explorer Sport-Trac Mustang RRRRRRRRRRRRRRRRRRRRRRRRRRRRRRRRRRRR																	
									R	R	F	F	F	F	F	F	F
								_	_	_							
	Mountaineer							R	R	R	F	F					
6R60/75/80	Explorer Sport-										-	-					
,,	Trac								R	R	F	F					
Trac F-150							F	F	F	F	F	F	F				
	Mustang												F	F	F	F	F
	Transit																F



GSB Overview:

This bulletin provides the process for using the transmission flush machine and provides an application reference chart.

NOTE:

This information is not intended to replace or supersede any warranty, parts and service policy, Work Shop Manual (WSM) procedures or technical training or wiring diagram information.

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the Bulletin applies to your vehicle.

Disclaimer