

2004 Ford Mustang V8-4.6L SOHC VIN X

Vehicle > Technical Service Bulletins

RESTRAINTS - SEAT BELT STOP BUTTON SERVICE

TSB 05-3-10

02/21/05

SAFETY BELT WEB STOP BUTTON SERVICE

FORD:

2000-2004 Mustang

2000-2005 Crown Victoria, Focus, Taurus

1999-2005 F-Super Duty

2000-2003 Windstar

2000-2005 Excursion, F-150, Ranger

2001-2003 Explorer Sport

2001-2005 Escape, Explorer Sport Trac

2002-2005 Explorer

2003-2004 Expedition

2004-2005 Freestar

2005 Escape Hybrid

LINCOLN:

2000-2005 LS, Town Car

2003-2004 Navigator

2003-2005 Aviator

MERCURY:

2000-2005 Sable

2001-2005 Mariner

2002-2005 Mountaineer

2004-2005 Monterey

ISSUE

To service a safety belt web stop button (the button that keeps the belt tongue from sliding down when not in use), a service kit is now available.

ACTION

Install the safety belt button kit, DO NOT replace the entire safety belt assembly. Follow the Service Procedure in the Instruction Sheet that comes with the kit. Refer to Section 501-20A of the appropriate model year Workshop Manual for additional information if needed.

NOTE

ONE KIT WILL REPAIR ONE SEAT BELT BUTTON.

PART NUMBER	PART NAME
YR3Z-6365070-AA	Seat Belt Button Kit

Parts Block

WARRANTY STATUS: Eligible Under Provisions Of New Vehicle Limited Warranty Coverage

DEALER CODING

CONDITION BASIC PART NO. CODE 70611B09 42

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the Bulletin applies to your vehicle.

Disclaimer